REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	9/24/2020	**Time:**	10:41 AM
Name of School Corporation:	PRIMROSE SCHOOL @ BRIDGEWATER			**Corp ID:**	290007
Address of School Corporation:	14711 N. Gray Rd.				
City:	Westfield	**Zip:**	46062	**County Number:**	29
VIN:	1GB0G2BA3D1180155	**License Number:**	1A	**Bus Number:**	1A
Make of Body:	Chevrolet **Year:** 2013	**Make of Chassis:**	Girardin Minibus, Inc.	**Year:**	2013
Bus Type:	A1	**Mileage:**	24679		
Inspection Status:	O	**Inspected By:**	Jeff Kastenschmidt	**PE:**	5805

Violations - Rejected

Inspection Code	Description
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
43-1-8	Any required lettering is missing or faded.
71-1-3	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**