REPORT OF SCHOOL BUS INSPECTION

Type of 8:39 Re-Inspection Date: 9/29/2020 Time: Inspection: ΑM Name of School Corporation: **INDIANA ACADEMY** Corp ID: 29B190 **Address of School Corporation:** 24815 SR 19 County City: Cicero Zip: 46034 29 Number: License VIN: 1BABKCXA94F219815 Bus Number: 2 2new Number: Blue Bird Make of Blue Bird Make of Body: Year: 2003 Year: 2004 Corporation Corporation Chassis: **Bus Type:** С Mileage: 86041 Inspection Inspected О Jeff Kastenschmidt PE: 5805 Status: By:

Violations - Rejected

Inspection Code	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
43-1-8	Any required lettering is missing or faded.
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
20-1-10	See Notes: Any defect inspector deems a violation not listed
69-1-7	See Notes: Any defect inspector deems a violation not listed
28-1-6	See Notes: Any defect inspector deems a violation not listed
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
22-1-1	A dripping oil or fluid leak
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	<u>Description</u>
11-2-2	A bumper does not meet manufactures specifications
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
57-2-1	Any part of the step-well or support structure is rusted through

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.