REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			Date:	10/1/2020	Time:	9:43 AM
Name of School Address of Scho	•		IEAST DUB 32 E 15th S	OIS CO. SCH. C	ORP	Corp ID:	192100
City:	Ferdinand	Zi	ip:	47532		County Number:	19
VIN:	1BAAHCPA01F202	2164		License Number:	B965B	Bus Number:	7
Make of Body:	Blue Bird Corporation	Year: 20	001	Make of Chassis:	Blue Bird Corporation	Year:	2001
Bus Type:	D			Mileage:	233878		
Inspection Status:	0	_	nspected By:	Mike Adams		PE:	7407

Violations - Rejected

Inspection Code	Description
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
2-1-1	Required back-up lights do not function.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.