REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	10/1/2020	**Time:**	9:44 AM
Name of School Corporation:	PRIMROSE SCHOOL @ GRAY EAGLE			**Corp ID:**	290003
Address of School Corporation:	12290 Olio Rd.				
City:	Fishers	**Zip:**	46037	**County Number:**	29
VIN:	1GBHG31V261253225	**License Number:**	B782AB	**Bus Number:**	1
Make of Body:	Chevrolet **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2006
Bus Type:	A1	**Mileage:**	26968		
Inspection Status:	O	**Inspected By:**	Jeff Kastenschmidt	**PE:**	5805

Violations - Rejected

Inspection Code	Description
43-1-8	Any required lettering is missing or faded.

Violations - Out of Service

Inspection Code	Description
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**