REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	10/2/2020	**Time:**	8:04 AM
Name of School Corporation:	PRIMROSE WEST CARMEL			**Corp ID:**	1100382
Address of School Corporation:	3746 W. 96th st				
City:	Carmel	**Zip:**	46032	**County Number:**	29
VIN:	1GBHG31C181231394	**License Number:**	B115K	**Bus Number:**	A1
Make of Body:	Chevrolet **Year:** 2008	**Make of Chassis:**	Collins Bus Corporation	**Year:**	2008
Bus Type:	A1	**Mileage:**	64020		
Inspection Status:	R	**Inspected By:**	Jeff Kastenschmidt	**PE:**	5805

Violations - Rejected

Inspection Code	Description
62-1-2	One (1) taillight or one (1) brake light does not function
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**