

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	10/2/2020	Time:	8:04 AM
Name of School Corporation:	PRIMROSE WEST CARMEL			Corp ID:	1100382
Address of School Corporation: 3746 W. 96th st					
City:	Carmel	Zip:	46032	County Number:	29
VIN:	1GBHG31C181231394	License Number: B115K		Bus Number:	A1
Make of Body:	Chevrolet	Year:	2008	Make of Chassis:	Collins Bus Corporation
Bus Type:	A1	Mileage: 64020		Year:	2008
Inspection Status:	R	Inspected By:	Jeff Kastenschmidt	PE:	5805

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.