

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/6/2020	Time:	9:12 AM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	Zip:	47140	County Number:	13
VIN:	4DRBUAAP98A499509	License Number:	J334112	Bus Number:	7
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation
Year:	2008	Mileage:	129677	PE:	7407
Bus Type:	C	Inspected By:	Mike Adams		
Inspection Status:	R				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.