

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 10/9/2020      **Time:** 12:02 PM  
**Name of School Corporation:** GEO FOUNDATION - INDY      **Corp ID:**  
**Address of School Corporation:** 3145 N. Meridian St  
**City:** Indianapolis      **Zip:** 46208      **County Number:** 49  
**VIN:** 1GB3GRBG4L1163700      **License Number:** TEMP      **Bus Number:** 201  
**Make of Body:** Chevrolet      **Year:** 2019      **Make of Chassis:** Chevrolet      **Year:** 2020  
**Bus Type:** A1      **Mileage:** 1864  
**Inspection Status:** O      **Inspected By:** Jeff Kastenschmidt      **PE:** 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
70-1-1	There is unapproved glazing material installed in the bus
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-1	There is no seat belt cutter in the vehicle

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.