

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection	Date: 10/15/2020	Time: 9:50 AM
Name of School Corporation: M.S.D. STEUBEN COUNTY	Corp ID: 767615	
Address of School Corporation: 400 S Martha St		
City: Angola	Zip: 46703	County Number: 76
VIN: 4UZABRDT4CCBA1157	License Number: 484	Bus Number: 25
Make of Body: Thomas Built Buses, Inc.	Year: 2012	Make of Chassis: Freightliner
Year: 2012	Mileage: 89005	Year: 2012
Bus Type: C		
Inspection Status: O	Inspected By: Eric Egbert	PE: 7006

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.