REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Semi-Annual | | | Date: | 10/15/2020 | Time: | 9:30 AM |
|------------------------|-----------------------------|-------|------------------|--------------------|--------------|-------------------|------------|
| Name of School C | orporation: | DECA | ATUR COUNT | Y COMM. SCHOO | L | Corp ID: | 161655 |
| Address of Schoo | l Corporation: | | 1645 W SR 4 | 6 | | | |
| City: | Greensburg | | Zip: | 47240 | | County Number: | 16 |
| VIN: | 4UZABRDJ28CZ15122 | | | License Number: | B380M | Bus Number: | 16 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2007 | Make of Chassis: | Freightliner | Year: | 2008 |
| Bus Type: | С | | | Mileage: | 37115 | | |
| Inspection Status: | 0 | | Inspected Bv: | Chris Clark | | PE: | 6665 |

Violations - Rejected

| <u>Inspection</u> <u>Code</u> | <u>Description</u> | | | | | |
|----------------------------------|--|--|--|--|--|--|
| 24-1-4 | Trim color is other than black | | | | | |
| 24-1-5 | Any paint is badly faded or peeling | | | | | |
| 2-1-1 | Required back-up lights do not function. | | | | | |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) | | | | | |
| 41-1-2 | Any interior protrusions have sharp edges or corners | | | | | |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) | | | | | |

Violations - Out of Service

| Inspection Code | <u>Description</u> |
|--------------------|---|
| 41-2-1 | Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students) |
| 7-2-8 | There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely |
| 7-2-1 | There is no brake certification form the certification is expired or is not signed within the six-month requirement |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more

| front of the windshie | eld. The entrance doo | r is behind the front | wheels. | persons. All of the e | engine is in |
|-----------------------|-----------------------|-----------------------|---------|-----------------------|--------------|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |