

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-----------------------------|------------------------|-------------|-------------------------|--------------|
| Type of Inspection: | Re-Inspection | Date: | 10/16/2020 | Time: | 9:39 AM |
| Name of School Corporation: | DECATUR COUNTY COMM. SCHOOL | Corp ID: | 161655 | | |
| Address of School Corporation: | 1645 W SR 46 | | | | |
| City: | Greensburg | Zip: | 47240 | County Number: | 16 |
| VIN: | 4UZABRDJ28CZ15122 | License Number: | B380M | Bus Number: | 16 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2007 | Make of Chassis: | Freightliner |
| Bus Type: | C | Mileage: | 37115 | | |
| Inspection Status: | O | Inspected By: | Chris Clark | PE: | 6665 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |
| 41-1-2 | Any interior protrusions have sharp edges or corners |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |
| 24-1-4 | Trim color is other than black |
| 24-1-5 | Any paint is badly faded or peeling |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 41-2-1 | Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students) |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.