

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 10/21/2020      **Time:** 10:12 AM  
**Name of School Corporation:** ADVENTURES CHILDCARE      **Corp ID:** 41DC1  
**Address of School Corporation:** 300 Western Blvd  
**City:** Greenwood      **Zip:** 46142      **County Number:** 41  
**VIN:** 1GB0GRBF8G1291485      **License Number:** B778M      **Bus Number:** GREEN  
**Make of Body:** Chevrolet      **Year:** 2016      **Make of Chassis:** Chevrolet      **Year:** 2016  
**Bus Type:** A1      **Mileage:** 29885  
**Inspection Status:** O      **Inspected By:** Jeff Kastenschmidt      **PE:** 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
62-1-3	Does not have four combination red brake lamps, two with minimum 38 sq inch illuminated (7" round) and two with a minimum of 12 sq inches illuminated area(4" round), mounted on the rear of the body between the belt line and floor line
50-1-1	The seat belt cutter is not located within the driver's view and reach

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
62-2-2	LED type lights have 50% or more pixels inoperable in one light

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.