REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	10/21/2020	**Time:**	10:12 AM
Name of School Corporation:	ADVENTURES CHILDCARE			**Corp ID:**	41DC1
Address of School Corporation:	300 Western Blvd				
City:	Greenwood	**Zip:**	46142	**County Number:**	41
VIN:	1GB0GRBF8G1291485	**License Number:**	B778M	**Bus Number:**	GREEN
Make of Body:	Chevrolet **Year:** 2016	**Make of Chassis:**	Chevrolet	**Year:**	2016
Bus Type:	A1	**Mileage:**	29885		
Inspection Status:	O	**Inspected By:**	Jeff Kastenschmidt	**PE:**	5805

Violations - Rejected

Inspection Code	Description
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
62-1-3	Does not have four combination red brake lamps, two with minimum 38 sq inch illuminated (7” round) and two with a minimum of 12 sq inches illuminated area(4” round), mounted on the rear of the body between the belt line and floor line
50-1-1	The seat belt cutter is not located within the driver’s view and reach

Violations - Out of Service

Inspection Code	Description
62-2-2	LED type lights have 50% or more pixels inoperable in one light

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**