

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/22/2020	Time:	10:18 AM
Name of School Corporation:	KOKOMO SCHOOL CORPORATION	Corp ID:	343500		
Address of School Corporation:	620 W Deffenbaugh				
City:	Kokomo	Zip:	46901	County Number:	34
VIN:	4DRBUC8N9GB732927	License Number:	9037	Bus Number:	230
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation
		Year:	2016		
Bus Type:	C	Mileage:	75043		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
55-1-6	See Notes: Any defect inspector deems a violation not listed
57-1-2	Step-well area is weakened

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
39-2-1	Inner fenders are loose from body or mounting brackets
51-2-1	The service door does not open or close properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.