

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/22/2020	Time:	11:40 AM
Name of School Corporation:	M.S.D. PIKE TOWNSHIP	Corp ID:	495350		
Address of School Corporation:	3950 W 56th St				
City:	Indianapolis	Zip:	46254	County Number:	49
VIN:	1BABNBPA5GF316211	License Number:	9850	Bus Number:	1052
Make of Body:	Blue Bird Corporation	Year:	2014	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	61747		
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
55-1-6	See Notes: Any defect inspector deems a violation not listed
68-1-1	Washers do not function properly in any manner
7-1-5	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
11-1-1	The front bumper does not extend to the edge of the fenders
20-1-10	See Notes: Any defect inspector deems a violation not listed
37-1-1	The horn does not operate at all

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with

a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.