

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/22/2020	Time:	5:16 PM		
Name of School Corporation:	CLAY COMMUNITY SCHOOLS			Corp ID:	111125		
Address of School Corporation:	PO Box 169						
City:	Knightsville	Zip:	47857	County Number:	11		
VIN:	1BAKJCSAXKF352946		License Number:	352946	Bus Number:	21	
Make of Body:	Blue Bird Corporation	Year:	2018	Make of Chassis:	Blue Bird Corporation	Year:	2019
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus
31-2-1	Frame is deteriorated, cracked, broken or severely bent
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.