## **REPORT OF SCHOOL BUS INSPECTION**

| Type of Inspection: | Re-Inspection       |               | Date:            | 11/4/2020      | Time:                 | 9:54 PM |
|---------------------|---------------------|---------------|------------------|----------------|-----------------------|---------|
| Name of School Co   | orporation: SOU     | THEAST DUBO   | IS CO. SCH. CORP | )              | Corp ID:              | 192100  |
| Address of School   | Corporation:        | 432 E 15th St |                  |                |                       |         |
| City:               | Ferdinand           | Zip:          | 47532            |                | <b>County Number:</b> | 19      |
| VIN:                | 1HVBBAAP42H5256     | 615           | License Number:  | B901J          | Bus Number:           | 7A      |
| Make of Body:       | IC Corporation Year | : 2001        | Make of Chassis: | IC Corporation | Year:                 | 2002    |
| Bus Type:           | С                   |               | Mileage:         | 152268         |                       |         |
| Inspection Status:  | А                   | Inspected By: | Mike Adams       |                | PE:                   | 7407    |

**Violations - Rejected** 

Inspection Code Description

Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.