REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	11/5/2020	Time:	8:50 AM
Name of School Address of Sch	I Corporation: SOU	JTH HARRISO 315 S Harri	ON COMM. SCH. son Dr	. CORP	Corp ID:	313190
City:	Corydon	Zip:	47112		County Number:	31
VIN:	4UZAAXCT64CM91206		License Number:	2204	Bus Number:	26
Make of Body:	Thomas Built Buses, Yea Inc.	r: 2003	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2003
Bus Type:	С		Mileage:	129152		
Inspection Status:	R	Inspected By:	Troy Boyd		PE:	5171

Violations - Rejected

Inspection Code Description

23-1-3 Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.