

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 11/12/2020 **Time:** 8:21 AM
Name of School Corporation: BLUE RIVER SERVICES **Corp ID:** 450001
Address of School Corporation: 3141 Progress Blvd.
City: Corydon **Zip:** 47112 **County Number:** 31
VIN: 1GBJG31U361188250 **License Number:** 21080 **Bus Number:** 99
Make of Body: Chevrolet **Year:** 2006 **Make of Chassis:** Chevrolet **Year:** 2006
Bus Type: A2 **Mileage:** 199314
Inspection Status: R **Inspected By:** Troy Boyd **PE:** 5171

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 62-1-2 | One (1) taillight or one (1) brake light does not function |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.