

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	11/12/2020	<b>Time:</b>	2:20 PM
<b>Name of School Corporation:</b>	MACONAQUAH SCHOOL CORPORATION	<b>Corp ID:</b>	525615		
<b>Address of School Corporation:</b>	7932 S Strawtown Pike				
<b>City:</b>	Bunker Hill	<b>Zip:</b>	46914	<b>County Number:</b>	52
<b>VIN:</b>	4UZABRFB2LCLH9296	<b>License Number:</b>	23104	<b>Bus Number:</b>	45
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2019	<b>Make of Chassis:</b>	Freightliner
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2020
<b>Bus Type:</b>	C	<b>Mileage:</b>	10533		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
25-2-2	Reflective glass is cracked, broken, or missing
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**