

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks Date: 11/19/2020 Time: 3:31 PM
Name of School Corporation: PRIMROSE SCHOOL OF W. FISHERS Corp ID: 290004
Address of School Corporation: 12609 Parkside Dr.
City: Fishers Zip: 46038 County Number: 29
VIN: 1GB3G2BG7D1166101 License Number: B839J Bus Number: 3
Make of Body: Chevrolet Year: 2013 Make of Chassis: Starcraft Year: 2013
Bus Type: A1 Mileage: 22479
Inspection Status: O Inspected By: Jeff Kastenschmidt PE: 5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-2	Any emergency device is in poor condition
26-1-8	See Notes: Any defect inspector deems a violation not listed
70-1-1	There is unapproved glazing material installed in the bus

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.