

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 11/19/2020 **Time:** 3:36 PM
Name of School Corporation: PRIMROSE SCHOOL OF W. FISHERS **Corp ID:** 290004
Address of School Corporation: 12609 Parkside Dr.
City: Fishers **Zip:** 46038 **County Number:** 29
VIN: 1GBHG31C081109884 **License Number:** B733D **Bus Number:** 1
Make of Body: Chevrolet **Year:** 2008 **Make of Chassis:** Chevrolet **Year:** 2008
Bus Type: A1 **Mileage:** 78290
Inspection Status: O **Inspected By:** Jeff Kastenschmidt **PE:** 5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
51-1-2	Protective padding is missing or damaged
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
70-1-1	There is unapproved glazing material installed in the bus
50-1-2	The seat belt cutter is not secured using a positive fastening method.
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**