

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks Date: 11/24/2020 Time: 9:11 AM  
Name of School Corporation: PRIMROSE SCHOOL OF W. FISHERS Corp ID: 290004  
Address of School Corporation: 12609 Parkside Dr.  
City: Fishers Zip: 46038 County Number: 29  
VIN: 1GBHG31C681181818 License Number: B930AC Bus Number: 2  
Make of Body: Chevrolet Year: 2008 Make of Chassis: Chevrolet Year: 2008  
Bus Type: A1 Mileage: 48147  
Inspection Status: O Inspected By: Jeff Kastenschmidt PE: 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-1	There is unapproved glazing material installed in the bus
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.