REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection			**Date:**	12/3/2020	**Time:**	3:06 PM
Name of School Corporation:	HEARTLAND HALL CHILD DEVELOPMENT CHENTER					**Corp ID:**	
Address of School Corporation:	11540 N Meridian Street						
City:	Carmel	**Zip:**	46032			**County Number:**	29
VIN:	1GBJG31U351192409			**License Number:**	B168A	**Bus Number:**	1
Make of Body:	Chevrolet	**Year:**	2005	**Make of Chassis:**	Chevrolet	**Year:**	2005
Bus Type:	A1			**Mileage:**	72539		
Inspection Status:	O	**Inspected By:**	Jeff Kastenschmidt			**PE:**	5805

Violations - Rejected

Inspection Code	Description
68-1-3	Reservoir is empty
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
61-1-5	See Notes: Any defect inspector deems a violation not listed
43-1-8	Any required lettering is missing or faded.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code	Description
50-2-1	There is no seat belt cutter in the vehicle
32-2-3	Tank cap is missing
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**