

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 1/14/2021 **Time:** 9:01 AM
Name of School Corporation: SWITZERLAND COUNTY SCHOOL CORP **Corp ID:** 787775
Address of School Corporation: 1040 W Main St
City: Vevay **Zip:** 47043 **County Number:** 78
VIN: 1GB3GSBG3G1276406 **License Number:** 41061 **Bus Number:** A1
Make of Body: Thomas Built Buses, Inc. **Year:** 2016 **Make of Chassis:** Chevrolet **Year:** 2016
Bus Type: A2 **Mileage:** 39423
Inspection Status: R **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
34-1-1	Any headlight is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**