

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	1/15/2021	Time:	10:31 AM
Name of School Corporation:	JOY'S HELPING HAND CHILD CARE			Corp ID:	222
Address of School Corporation:	3807 W. Michigan St,				
City:	Indianapolis	Zip:	46224	County Number:	49
VIN:	1GBJG31U331161738		B685N	Bus Number:	422
Make of Body:	Chevrolet	Year:	2003	Make of Chassis:	Chevrolet
Bus Type:	A2			Mileage:	36321
Inspection Status:	O	Inspected By:	Rob Hawkins	PE:	5199

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
43-1-2	Lettering on the sides: are any color other than black, or more than six (6) or less than four (4) inches in height.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design)

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.