REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			Date:	1/20/2021	Time:	10:11 AM
Name of School Corporation: Address of School Corporation:		EAST	EAST PORTER COUNTY SCHOOL CORP PO Box 370		Corp ID:	646510	
City:	Kouts		Zip:	46347		County Number:	64
VIN:	4UZABRFC3KCJZ5495	5		License Number:	21220	Bus Number:	33
Make of Body:	Thomas Built Buses, Inc.	Year:	2017	Make of Chassis:	Freightliner	Year:	2019
Bus Type:	С			Mileage:	17049		
Inspection Status:	0		Inspected By:	Tim Grayson		PE:	7558

Violations - Rejected

Inspection Cod	<u>Description</u>
34-1-1	Any headlight is inoperative
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code	<u>Description</u>
34-2-1	Both lamps are inoperative on low beam
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
31-2-1	Frame is deteriorated, cracked, broken or severely bent
11-2-2	A bumper does not meet manufactures specifications
7-2-3	The required low air-pressure warning device fails to operate properly
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
22-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in

front of the windshield	The entrance door is behind the front wheels.
mont of the windsinera.	The childrice door is belined the front wheels.