

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/29/2021	Time:	12:35 PM
Name of School Corporation:	NORTH CENTRAL PARKE COMM SCH CORP			Corp ID:	616375
Address of School Corporation:	1497 E STATE RD 47				
City:	MARSHALL	Zip:	47859	County Number:	61
VIN:	1BAKGCPH2GF318902	License Number:			GF318902
Make of Body:	Blue Bird Corporation	Year:	2015	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	47936	Year:	2016
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.