## REPORT OF SCHOOL BUS INSPECTION

Type of 7:15 Re-Inspection Date: 2/11/2021 **Time**: Inspection: AM Name of School Corporation: EAST PORTER COUNTY SCHOOL CORP 646510 Corp ID: **Address of School Corporation:** PO Box 370 County City: Kouts Zip: 46347 64 Number: License VIN: 4UZABRDJ9ACAM0209 32179 **Bus Number:** 29 Number: Make of Thomas Built Buses, Year: 2008 Freightliner Year: Make of Body: 2010 Inc. Chassis: С Mileage: 88413

Bus Type:

Inspected PE: **Inspection Status:** O Nathan Sherer 7029 By:

## Violations - Rejected

<u>Inspection</u>	Description
<u>Code</u>	<u>Description</u>

The bus body has loose, damaged or improperly aligned body parts. These would 24-1-2 include rivets, bolts, and body panels and/or rub rails

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus
25-2-2	Reflective glass is cracked, broken, or missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.