

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |               |                         |                          |              |      |
|---------------------------------------|--------------------------------|------------------------|---------------|-------------------------|--------------------------|--------------|------|
| <b>Type of Inspection:</b>            | Post-Crash Inspection          | <b>Date:</b>           | 2/11/2021     | <b>Time:</b>            | 2:45 PM                  |              |      |
| <b>Name of School Corporation:</b>    | NORTH PUTNAM COMMUNITY SCHOOLS |                        |               | <b>Corp ID:</b>         | 676715                   |              |      |
| <b>Address of School Corporation:</b> | Box 169                        |                        |               |                         |                          |              |      |
| <b>City:</b>                          | Bainbridge                     | <b>Zip:</b>            | 46105         | <b>County Number:</b>   | 67                       |              |      |
| <b>VIN:</b>                           | 1GB3GSBG8K1174334              | <b>License Number:</b> | 24043         | <b>Bus Number:</b>      | 421                      |              |      |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.       | <b>Year:</b>           | 2019          | <b>Make of Chassis:</b> | Thomas Built Buses, Inc. | <b>Year:</b> | 2021 |
| <b>Bus Type:</b>                      |                                | <b>Mileage:</b>        | 9545          |                         |                          |              |      |
| <b>Inspection Status:</b>             | <input type="radio"/>          | <b>Inspected By:</b>   | Byron Goodman | <b>PE:</b>              | 7008                     |              |      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 11-1-2                 | The front or rear bumper is not properly attached, missing, torn, loose, or altered.  |
| 34-1-1                 | Any headlight is inoperative  |
| 24-1-2                 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 64-1-4                 | Any front turn signal does not function properly  |
| 64-1-1                 | Turn signals are not properly mounted   |
| 33-1-1                 | The grill has any exposed edges that may cause injury   |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 24-2-1                 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |

### Bus Type Description