REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	2/19/2021	Time:	2:15 PM
Name of School Corpo	ration: RICH	IMOND COMMU	JNITY SCHOOL CO	DRP	Corp ID:	898385
Address of School Cor	poration:	3175 north sali	sbury road			
City:	richmond	Zip:	47374		County Number:	89
VIN:	1FDFE4FP	7ADA22882	License Number:	84278	Bus Number:	75
Make of Body:	Ford Year	: 2009	Make of Chassis:	Ford	Year:	2009
Bus Type:			Mileage:	21316		
Inspection Status:	А	Inspected By:	Jeremy Mason		PE:	8139

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description