

## REPORT OF SCHOOL BUS INSPECTION

|   |                                  |  |
|---|----------------------------------|--|
| <b>Type of Inspection:</b> Annual                                 | <b>Date:</b> 2/22/2021           | <b>Time:</b> 10:22 AM                  |
| <b>Name of School Corporation:</b> SUNMAN-DEARBORN COMM. SCH CORP | <b>Corp ID:</b> 151560           |  |
| <b>Address of School Corporation:</b> 1 Trojan Place STE B        |                                  |  |
| <b>City:</b> St Leon  | <b>Zip:</b> 47012                | <b>County Number:</b> 15               |
| <b>VIN:</b> 4DRBWAARX6A211764                                     | <b>License Number:</b> B754C     | <b>Bus Number:</b> 14                  |
| <b>Make of Body:</b> IC Corporation                               | <b>Year:</b> 2005                | <b>Make of Chassis:</b> IC Corporation |
| <b>Year:</b> 2006   | <b>Mileage:</b> 124180           | <b>PE:</b> 6665                        |
| <b>Bus Type:</b> D  | <b>Inspected By:</b> Chris Clark |  |
| <b>Inspection Status:</b> R                                       |                                  |  |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 40-1-2                 | Any required instrument or gauge is inoperative. (Speedometer, Odometer, Fuel Gauge, High beam, Brake indicator light or gauge, air pressure gauge, brake warning light, DEF Gauge) |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.