

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/22/2021	Time:	6:07 PM		
Name of School Corporation:	M.S.D. SHAKAMAK SCHOOLS			Corp ID:	282960		
Address of School Corporation:	RR 2 Box 42						
City:	Jasonville	Zip:	47438	County Number:	28		
VIN:	4DRBUAAP0DB184649		License Number:	3566	Bus Number:	6	
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2013
Bus Type:	C			Mileage:	66064		
Inspection Status:	O	Inspected By:	Mark Raper	PE:	6473		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-3	There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-1	The front bumper does not extend to the edge of the fenders
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
25-1-1	Mirror or mirror backs that are loose or improperly mounted

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly
70-2-1	Any glass or glazing is broken through or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
25-2-2	Reflective glass is cracked, broken, or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.