REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:2/23/2021Time:8:29 AMName of School Corporation: NORTH LAWRENCE COMM. SCHOOLSCorp ID:475075

Address of School Corporation: 595 Stars Blvd

City:BedfordZip:47421County Number:47VIN:4uzabrdt88cz11044License Number:1236Bus Number:2PVMake of Body:Titan Bus Year:2007Make of Chassis:Freightliner Year:2008

Bus Type: C Mileage: 88543

Inspection Status: O Inspected By: Travis Coryea PE: 5892

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

70-1-12 See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

32-2-1 There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.