

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 2/23/2021 **Time:** 8:29 AM
Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS **Corp ID:** 475075
Address of School Corporation: 595 Stars Blvd
City: Bedford **Zip:** 47421 **County Number:** 47
VIN: 4uzabrdt88cz11044 **License Number:** 1236 **Bus Number:** 2PV
Make of Body: Titan Bus **Year:** 2007 **Make of Chassis:** Freightliner **Year:** 2008
Bus Type: C **Mileage:** 88543
Inspection Status: O **Inspected By:** Travis Coryea **PE:** 5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-12	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.