

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	2/26/2021	<b>Time:</b>	9:11 AM
<b>Name of School Corporation:</b>	SOUTHEAST DUBOIS CO. SCH. CORP	<b>Corp ID:</b>	192100		
<b>Address of School Corporation:</b>	432 E 15th St				
<b>City:</b>	Ferdinand	<b>Zip:</b>	47532	<b>County Number:</b>	19
<b>VIN:</b>	1GBL7T1C41J509074	<b>License Number:</b>	B625C	<b>Bus Number:</b>	10
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2001	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2002	<b>Year:</b>	2002		
<b>Bus Type:</b>	C	<b>Mileage:</b>	166690		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Mike Adams	<b>PE:</b>	7407

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-1	The latch does not secure the hood tightly
36-1-3	See Notes: Any defect inspector deems a violation not listed
11-1-7	See Notes: Any defect inspector deems a violation not listed
82-1-2	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**