REPORT OF SCHOOL BUS INSPECTION

Type of 4:48 Post-Crash Inspection Date: 3/15/2021 Time: Inspection: PM HAMILTON SOUTHEASTERN SCHOOLS 293005 Name of School Corporation: Corp ID: **Address of School Corporation:** 13485 Cumberland Rd County City: **Fishers** Zip: 46038 29 Number: License VIN: 1T7YR4E2191114173 31677 Bus Number: 9 Number: Thomas Built Buses, Year: 2008 Thomas Built Buses, Year: Make of Make of Body: 2009 Inc. Inc. Chassis: **Bus Type:** D Mileage: 95958 Inspection Inspected 0 PE: Jeff Kastenschmidt 5805 Status: By:

Violations - Rejected

Inspection Code	<u>Description</u>
80-1-8	See Notes: Any defect inspector deems a violation not listed
11-1-7	See Notes: Any defect inspector deems a violation not listed
34-1-1	Any headlight is inoperative

Violations - Out of Service

Inspection Code	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.