REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/17/2021	**Time:**	10:58 AM
Name of School Corporation:	CENTRAL NINE VOC-TECH SCHOOL			**Corp ID:**	414265
Address of School Corporation:	1999 US 31 S				
City:	Greenwood	**Zip:**	46142	**County Number:**	41
VIN:	4DRBUAAN28B499568	**License Number:**	4823	**Bus Number:**	11
Make of Body:	IC Corporation **Year:** 2007	**Make of Chassis:**	IC Corporation	**Year:**	2007
Bus Type:	C	**Mileage:**	65457		
Inspection Status:	O	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
43-1-8	Any required lettering is missing or faded.
48-1-1	Power steering unit leaks at any point
41-1-2	Any interior protrusions have sharp edges or corners
59-1-15	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.