

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/17/2021	Time:	10:58 AM		
Name of School Corporation:	CENTRAL NINE VOC-TECH SCHOOL			Corp ID:	414265		
Address of School Corporation:	1999 US 31 S						
City:	Greenwood	Zip:	46142	County Number:	41		
VIN:	4DRBUAAN28B499568		License Number:	4823	Bus Number:	11	
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation	Year:	2007
Bus Type:	C			Mileage:	65457		
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
43-1-8	Any required lettering is missing or faded.
48-1-1	Power steering unit leaks at any point
41-1-2	Any interior protrusions have sharp edges or corners
59-1-15	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.