REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/19/2021	**Time:**	10:33 AM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31V061173292	**License Number:**	B201G	**Bus Number:**	3
Make of Body:	Chevrolet **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2006
Bus Type:	A2	**Mileage:**	54346		
Inspection Status:	R	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
22-1-1	A dripping oil or fluid leak
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
28-1-6	See Notes: Any defect inspector deems a violation not listed
61-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**