

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/22/2021	<b>Time:</b>	10:15 AM
<b>Name of School Corporation:</b>	FRANKLIN COMM. SCHOOL CORP.			<b>Corp ID:</b>	414225
<b>Address of School Corporation:</b>	750 E SR 44				
<b>City:</b>	Franklin	<b>Zip:</b>	46131	<b>County Number:</b>	41
<b>VIN:</b>	4drbuaan6db198456	<b>License Number:</b>	C929286	<b>Bus Number:</b>	115
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2012	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2013
<b>Bus Type:</b>	C	<b>Mileage:</b>	147864		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Jeff Kastenschmidt	<b>PE:</b>	5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-4	There is a significant fluid leak from the transmission
70-1-9	If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus
50-1-3	The seat belt cutter is contained in a compartment.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**