

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                 |                        |                    |                         |          |
|---------------------------------------|---------------------------------|------------------------|--------------------|-------------------------|----------|
| <b>Type of Inspection:</b>            | Re-Inspection                   | <b>Date:</b>           | 3/22/2021          | <b>Time:</b>            | 10:59 AM |
| <b>Name of School Corporation:</b>    | SMALL MIRACLES CHILDRENS CENTER | <b>Corp ID:</b>        | 49026Z             |                         |          |
| <b>Address of School Corporation:</b> | 3611 Ferguson Rd                |                        |                    |                         |          |
| <b>City:</b>                          | Indianapolis                    | <b>Zip:</b>            | 46204              | <b>County Number:</b>   | 49       |
| <b>VIN:</b>                           | 1GDHG31RXY1241594               | <b>License Number:</b> | B521AD             | <b>Bus Number:</b>      | 2        |
| <b>Make of Body:</b>                  | Girardin Minibus, Inc.          | <b>Year:</b>           | 2000               | <b>Make of Chassis:</b> | GMC      |
| <b>Bus Type:</b>                      |                                 | <b>Mileage:</b>        | 111530             | <b>Year:</b>            | 2000     |
| <b>Inspection Status:</b>             | O                               | <b>Inspected By:</b>   | Jeff Kastenschmidt | <b>PE:</b>              | 5805     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 22-1-1                 | A dripping oil or fluid leak   |
| 41-1-5                 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                        |
|------------------------|---|
| 8-2-5                  | There is brake fluid leaking at any point |

### Bus Type Description