

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 3/29/2021      **Time:** 12:52 PM  
**Name of School Corporation:** THE PLAYSCHOOL DAYCARE (29)      **Corp ID:** 290030  
**Address of School Corporation:** 11501 E 116th St.  
**City:** Fishers      **Zip:** 46037      **County Number:** 29  
**VIN:** 1GBHG31V751127859      **License Number:** B845L      **Bus Number:** 1  
**Make of Body:** Chevrolet      **Year:** 2004      **Make of Chassis:** Chevrolet      **Year:** 2005  
**Bus Type:** A2      **Mileage:** 44584  
**Inspection Status:** O      **Inspected By:** Jeff Kastenschmidt      **PE:** 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
43-1-8	Any required lettering is missing or faded.
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
50-1-2	The seat belt cutter is not secured using a positive fastening method.
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
62-1-1	Any lens is cracked, missing, faded or of the wrong color

### Violations - Out of Service

Inspection Code      Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.