

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	3/29/2021	Time:	12:54 PM		
Name of School Corporation:	THE PLAYSCHOOL DAYCARE (29)			Corp ID:	290030		
Address of School Corporation:	11501 E 116th St.						
City:	Fishers	Zip:	46037	County Number:	29		
VIN:	1GBHG31R221186428		License Number:	B764L	Bus Number:	3	
Make of Body:	Chevrolet	Year:	2002	Make of Chassis:	Chevrolet	Year:	2002
Bus Type:	A2			Mileage:	76045		
Inspection Status:	O	Inspected By:	Jeff Kastenschmidt	PE:	5805		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-1	Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
11-1-3	Bumpers are not black
16-1-2	See Notes: Any defect inspector deems a violation not listed
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
57-2-1	Any part of the step-well or support structure is rusted through
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.
20-2-4	Emergency door is not securely fastened to body

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.