REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date**: 3/29/2021 **Time**: 12:54 PM **Name of School Corporation**: THE PLAYSCHOOL DAYCARE (29) **Corp ID**: 290030

Address of School Corporation: 11501 E 116th St.

City:FishersZip:46037County Number:29VIN:1GBHG31R221186428License Number:Break Bus Number:3Make of Body:Chevrolet Year:2002Make of Chassis:Chevrolet Year:2002

Bus Type: A2 Mileage: 76045

Inspection Status: O Inspected By: Jeff Kastenschmidt PE: 5805

Violations - Rejected

Inspection Code	<u>Description</u>
67-1-1	Rims and wheels are painted any other color than black or gray. (Aluminum wheels may be of natural color) (MFSAB's are permitted to have factory wheels)
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
11-1-3	Bumpers are not black
16-1-2	See Notes: Any defect inspector deems a violation not listed
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

Violations - Out of Service

Inspection Code	<u>Description</u>
57-2-1	Any part of the step-well or support structure is rusted through
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half ($\frac{1}{2}$) inch in diameter.
20-2-4	Emergency door is not securely fastened to body

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.