## REPORT OF SCHOOL BUS INSPECTION

9:52 Type of Annual Date: 3/30/2021 **Time**: Inspection: AM Name of School Corporation: PERU COMMUNITY SCHOOLS 525635 Corp ID: **Address of School Corporation:** 35 W 3rd St County City: Peru Zip: 46970 52 Number: License VIN: 1GB6G5BGXF1102054 031241 **Bus Number:** Tiger3 Number: Make of Thomas Built Buses, Chevrolet Year: Year: 2015 Make of Body: 2015 Inc. Chassis: **Bus Type:** A2 Mileage: 85946 Inspected PE: **Inspection Status:** O Randy McPike 7018 By:

# Violations - Rejected

# Inspection Code Description 17-1-1 Any dome light is inoperative

35-1-1 A heater motor is not operating properly

## **Violations - Out of Service**

### Inspection Code Description

8-2-1 There is no brake certification, or the certification has expired or is not signed

### **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.