## REPORT OF SCHOOL BUS INSPECTION

Time: 9:32 AM **Type of Inspection:** Annual Date: 4/1/2021

Name of School Corporation: BENTON COMMUNITY SCHOOL CORP. Corp ID: 40395

**Address of School Corporation:** PO Box 512

City: Fowler Zip: 47944 **County Number: 4** VIN: 4DRBUC8N6FB709555 **Bus Number:** License Number: 9003 1441 Make of Body: Make of Chassis: IC Corporation Year: 2015 IC Corporation Year: 2014

**Bus Type:** С Mileage: 58867

PE: 7421 **Inspection Status:** R Inspected By: Nate King

## **Violations - Rejected**

Description **Inspection Code** 

64-1-5 LED type lights have 25% to 49% of the pixels inoperable in any one light

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.