REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/8/2021 **Time:** 9:15 AM **Name of School Corporation:** HONEY GROVE EDUCATIONAL DAYCARE **Corp ID:** 41001Z

Address of School Corporation: 1709 S SR 135

City:GreenwoodZip:46143County Number:41VIN:1GBHG31RXX1146766License Number:B958ABBus Number:2Make of Body:Chevrolet Year:1999Make of Chassis:Chevrolet Year:1999

Bus Type: Mileage: 129002

Inspection Status: O Inspected By: Jeff Kastenschmidt PE: 5805

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

70-1-1 There is unapproved glazing material installed in the bus 41-1-3 There is loose or unprotected wiring in passenger area

Violations - Out of Service

<u>Inspection Code</u> <u>Description</u>

64-2-1 Any rear turn signal does not function properly

Bus Type Description