

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual                      **Date:** 4/8/2021                      **Time:** 9:15 AM  
**Name of School Corporation:** HONEY GROVE EDUCATIONAL DAYCARE                      **Corp ID:** 41001Z  
**Address of School Corporation:** 1709 S SR 135  
**City:** Greenwood                      **Zip:** 46143                      **County Number:** 41  
**VIN:** 1GBHG31RXX1146766                      **License Number:** B958AB                      **Bus Number:** 2  
**Make of Body:** Chevrolet                      **Year:** 1999                      **Make of Chassis:** Chevrolet                      **Year:** 1999  
**Bus Type:**                      **Mileage:** 129002  
**Inspection Status:** O                      **Inspected By:** Jeff Kastenschmidt                      **PE:** 5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-1	There is unapproved glazing material installed in the bus
41-1-3	There is loose or unprotected wiring in passenger area

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly

### Bus Type Description