REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/8/2021	**Time:**	9:15 AM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31RXX1146766	**License Number:**	B958AB	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1999	**Make of Chassis:**	Chevrolet	**Year:**	1999
Bus Type:		**Mileage:**	129002		
Inspection Status:	O	**Inspected By:**	Jeff Kastenschmidt	**PE:**	5805

Violations - Rejected

Inspection Code	Description
70-1-1	There is unapproved glazing material installed in the bus
41-1-3	There is loose or unprotected wiring in passenger area

Violations - Out of Service

Inspection Code	Description
64-2-1	Any rear turn signal does not function properly

Bus Type Description